

```
1  OBDeleven data log
2
3  Date: 2024-08-12 15:32
4
5  VIN: WVWZZZ3CZKE074519
6  Car: Volkswagen Passat Alltrack
7  Year: 2019
8  Body type: Variant
9  Engine: DFHA
10 Mileage: 171523 KM
11
12 -----
13 01 Engine
14
15   System description: R4 2.0l TDI
16   Software number: 04L906026KA
17   Software version: 6014
18   Hardware number: 04L907309P
19   Hardware version: H25
20   ODX name: EV_ECM20TDI01104L906026KA
21   ODX version: 005004
22   Long coding: 0125041204761D083000
23
24   Trouble codes:
25       P20EE00 - SCR NOx Catalyst Efficiency Below Threshold Bank 1 Catalyst 1
26       Intermittent
27       P26FA00 - Coolant Pump "C" Air in System
28       Intermittent
29           Date: 2024-06-24 16:05:17
30           Mileage: 171499 km
31           Priority: 2
32           Malfunction frequency counter: 1
33           Unlearning counter: 255
34           Engine speed: 736.50 1/min
35           Normed load value: 62.0 %
36           Vehicle speed: 0 km/h
37           Coolant temperature: 111 °C
38           Intake air temperature: 55 °C
39           Ambient air pressure: 1010 mbar
40           Voltage terminal 30: 14.200 V
41           Dynamic environmental data:
42               209626106C0311A600001139054710FB132D16250BB412FB0C26
43
44 -----
45 02 Transmission
46
47   System description: GSG DQ381
48   Software number: 0GC300013K
49   Software version: 2403
50   Hardware number: 0GC927711H
51   Hardware version: H06
52   ODX name: EV_TCMDQ381061
53   ODX version: 001□□□
54   Long coding: 0014
55
56   Trouble codes:
57       No trouble codes found
58
59 -----
60 03 Brakes
61
62   System description: ESC
63   Software number: 5Q0614517DH
64   Software version: 0754
65   Hardware number: 5Q0614517AH
66   Hardware version: H62
67   Serial number: 60399000000175
68   ODX name: EV_Brake1UDSContiMK100IPB
69   ODX version: 037009
70   Long coding:
71       40EC6A8F34270B70477C070160CC4902562CD0E2E006927938625078EAA9420B00010312121212B435
72       351919323200
```

08 Air Conditioning

Subsystems:

Trouble codes:

09 Central Electrics

Subsystems:

```
System description: E1 - LDS MQB
Software version: 0032
Hardware version: H01
Serial number: 28 08 2018 10000745
```

144 System description: Sensor, DWA
145 Software version: 0316
146 Hardware version: 005
147 Serial number: 0000000000ZY183361JHH
148
149 System description: Sirene, DWA
150 Software version: 0007
151 Hardware version: 004
152 Serial number: 000000000000000308838
153
154 System description: Lenks.Modul
155 Software version: 0170
156 Hardware version: H23
157 Serial number: 0100010220190C200110
158

159 Trouble codes:
160 B140A4B - Central locking Excess temp.
161 Intermittent
162
163
164

165 13 Adaptive Cruise Control
166

167 System description: ACC BOSCH MQB
168 Software number: 3Q0907572C
169 Software version: 0196
170 Hardware number: 3Q0907572C
171 Hardware version: H05
172 ODX name: EV_ACCBOSCHVW48X
173 ODX version: 001009
174 Long coding: 320467DA55FFC728949C8045
175

176 Trouble codes:
177 No trouble codes found
178

180 15 Airbag
181

182 System description: Airbag VW21
183 Software number: 3Q0959655BG
184 Software version: 0712
185 Hardware number: 3Q0959655BG
186 Hardware version: 006
187 Serial number: 003W3P22ZKMF
188 ODX name: EV_AirbaVW21TS6VW48X
189 ODX version: 001014
190 Long coding: 88CCC000000000005C5400CF000800000065
191

192 Subsystems:

193 System description: SideSensor_Df
194 Software version: 0887
195 Hardware version: 008
196 Serial number: 357000000005B65C973U
197 Long coding: 2D2D2D
198

199 System description: SideSensor_Pf
200 Software version: 0887
201 Hardware version: 008
202 Serial number: 358000000000DBA48483Y
203 Long coding: 2D2D2D
204

205 System description: SideSensor_Dr
206 Software version: 0148
207 Hardware version: 301
208 Serial number: 35100E36F9717000000S
209 Long coding: 2D2D2D
210

211 System description: SideSensor_Pr
212 Software version: 0148
213 Hardware version: 301
214 Serial number: 3520056199617000000B
215 Long coding: 2D2D2D
216

```
217         System description: FrontSensor_D
218         Software version: 0149
219         Hardware version: 304
220         Serial number: 35500872A3F17000000N
221         Long coding: 2D2D2D
222
223     Trouble codes:
224         No trouble codes found
225
226 -----
227 17 Dashboard
228
229     System description: KOMBI
230     Software number: 3G0920751D
231     Software version: 2700
232     Hardware number: 3G0920751D
233     Hardware version: 310
234     ODX name: EV_DashBoardVDDMQBAB
235     ODX version: 009068
236     Long coding: 07A4080BEF8C000801886B2B1001000000000000
237
238     Trouble codes:
239         No trouble codes found
240
241 -----
242 19 Gateway
243
244     System description: GW MQB High
245     Software number: 3Q0907530AA
246     Software version: 5366
247     Hardware number: 3Q0907530C
248     Hardware version: 521
249     Serial number: 08011910803791
250     ODX name: EV_GatewNF
251     ODX version: 013025
252     Long coding: 0B0300345F087300FB10225A1A0F00010001070000000000000000000000
253
254     Subsystems:
255         System description: 0-00-05-00-04
256
257         System description: J367-BDMConti
258         Software version: 1051
259         Hardware version: H03
260         Serial number: 75886003001901251EBA
261
262         System description: U13DCAC
263         Software version: 0810
264         Hardware version: H27
265         Serial number: 3077411
266
267         System description: E221__MFL-DC1
268         Software version: 0052
269         Hardware version: H17
270         Serial number: 231900000034850039023
271         Long coding: 2FFFFFF
272
273         System description: Analoguhr
274         Software version: 1004
275         Hardware version: 111
276         Serial number: 2101201900010340
277
278     Trouble codes:
279         No trouble codes found
280
281 -----
282 22 All Wheel Control
283
284     System description: Haldex4Motion
285     Software number: 0CQ907554J
286     Software version: 7084
287     Hardware number: 0CQ525130
288     Hardware version: H55
289     Serial number: HA1-00017.01.1900010876
```

```
290         ODX name: EV_AllWheelContrHA1VW37X
291         ODX version: 004013
292         Long coding: 0301
```

Trouble codes:
No trouble codes found

3C Lane Change Assistant Right

```
System description: MRR1Rear
Software number: 3Q0907566G
Software version: 0530
Hardware number: 3Q0907566
Hardware version: H23
ODX name: EV_RearRadarS1BoschVW48X
ODX version: 001007
Long coding: 14C002
```

Trouble codes:
No trouble codes found

42 Driver Door

```
System description: TSG FS
Software number: 5Q0959593F
Software version: 0287
Hardware number: 5Q0959593F
Hardware version: 001
Serial number: YE007SAO38814
ODX name: EV_DCU2DriveSideMAXHKLO
ODX version: 001010
Long coding: 00350A20D0000200000001000
```

```
Trouble codes:
  B122D29 - Lock unit for central locking Implausible signal
    Intermittent
      Date: 2024-06-24 15:33:32
      Mileage: 171492 km
      Priority: 5
      Malfunction frequency counter: 3
      Unlearning counter: 45
```

44 Steering Assistance

```
System description: MQB_VWBS_GEN2
Software number: 5Q0910143C
Software version: 2211
Hardware number: 5Q0910143
Hardware version: 212
Serial number: 918003 00
ODX name: EV_SteerAssisVWBSMQBGen2
ODX version: 002119
Long coding: 0100001100400110
```

Trouble codes:
No trouble codes found

4B Multifunction Module

```
System description: FCM MQB Low
Software number: 3Q0907338C
Software version: 0345
Hardware number: 3Q0907338C
Hardware version: 002
Serial number: 03021910520620
ODX name: EV_MultiModulContiVW48X
ODX version: 002006
Long coding: 000000006090003D20000
```

363
364 Trouble codes:
365 No trouble codes found
366
367 -----
368 52 Passenger Door
369
370 System description: TSG BFS
371 Software number: 5Q0959592F
372 Software version: 0287
373 Hardware number: 5Q0959592F
374 Hardware version: 001
375 Serial number: YE007SA210125
376 ODX name: EV_DCU2PasseSideMAXHKLO
377 ODX version: 001010
378 Long coding: 00350020DC00020000001000
379
380 Trouble codes:
381 B122D29 - Lock unit for central locking Implausible signal
382 Intermittent
383 Date: 2024-02-12 07:28:59
384 Mileage: 168817 km
385 Priority: 5
386 Malfunction frequency counter: 15
387 Unlearning counter: 44
388
389 -----
390
391 5F Multimedia
392
393 System description: MU-S-N-ER
394 Software number: 3Q0035846B
395 Software version: 0478
396 Hardware number: 3Q0035846B
397 Hardware version: H41
398 Serial number: VWZAZ2W0257685
399 ODX name: EV_MUStd4CTSAT
400 ODX version: 001022
401 Long coding: 02840201FF0000005111000100080A031F0508C4012001008F
402
403 Subsystems:
404 System description: ABT_Std-2_Nav
405 Software version: 8130
406 Hardware version: H52
407 Serial number: VWZ6ZHW0414348
408
409 System description: ECE AS 22/23
410 Software version: 1810
411 Hardware version: ---
412 Serial number: -----
413
414 Trouble codes:
415 B201A00 - Checking software version management
416 static
417 Date: 2023-08-26 18:29:31
418 Mileage: 147739 km
419 Priority: 6
420 Malfunction frequency counter: 1
421 Unlearning counter: 46
422 Dynamic environmental data: 028686100200
423 B200087 - Control module Software incompatible
424 static
425 Date: 2023-08-26 19:57:41
426 Mileage: 147743 km
427 Priority: 6
428 Malfunction frequency counter: 1
429 Unlearning counter: 46
430 Dynamic environmental data: 02868710030401016F6E6C696E6500
431
432 -----
433
434 69 Trailer Control
435

436 System description: Anhaenger
437 Software number: 5Q0907383N
438 Software version: 0264
439 Hardware number: 5Q0907383N
440 Hardware version: H27
441 Serial number: 0506595109
442 ODX name: EV_TrailFunctGener2Hella
443 ODX version: 001008
444 Long coding: 0100000202000000
445

446 Trouble codes:
447 No trouble codes found
448

449 -----
450 6C Rear View Camera

451
452 System description: RVC Compact
453 Software number: 5Q0980556B
454 Software version: 0231
455 Hardware number: 5Q0980556B
456 Hardware version: H15
457 ODX name: EV_CamSysRVRVCPANAMQBAB
458 ODX version: 006009
459 Long coding: 0184420163002017000040
460

461 Trouble codes:
462 No trouble codes found
463

464 -----
465 6D Deck Lid Control

466
467 System description: HDSG-Modul
468 Software number: 5Q0959107P
469 Software version: 0266
470 Hardware number: 5Q0959107J
471 Hardware version: H13
472 Serial number: 32297291900000
473 ODX name: EV_DeckLidCONTIAU736
474 ODX version: 001016
475 Long coding: 0280
476

477 Trouble codes:
478 No trouble codes found
479

480 -----
481 76 Parking Assistance

482
483 System description: PDC 8 Kanal
484 Software number: 5QA919294E
485 Software version: 0443
486 Hardware number: 5QA919294
487 Hardware version: H07
488 Serial number: 00030841801902420661
489 ODX name: EV_EPHVA18AU3700000
490 ODX version: 009035
491 Long coding: 0471155911
492

493 Trouble codes:
494 No trouble codes found
495

496 -----
497 A5 Driver Assistance

498
499 System description: MQB_B_MFK
500 Software number: 3Q0980653F
501 Software version: 0171
502 Hardware number: 3Q0980653
503 Hardware version: H13
504 Serial number: 06011912K10313
505 ODX name: EV_MFKBoschMQBB
506 ODX version: 001001
507 Long coding: 00040802040004010026134F8150A900980094300040
508

509 Trouble codes:
510 No trouble codes found
511
512 -----
513 B7 Start System Interface
514
515 System description: VWKESSYMQB
516 Software number: 3Q0959435K
517 Software version: 1204
518 Hardware number: 3Q0959435K
519 Hardware version: 027
520 Serial number: 6097527865
521 ODX name: EV_KessyHellaMQBAB
522 ODX version: 004046
523 Long coding: 002F0F0723
524
525 Trouble codes:
526 U140000 - Function restriction due to insufficient voltage
527 Intermittent
528 Date: 2024-03-11 06:07:17
529 Mileage: 171301 km
530 Priority: 6
531 Malfunction frequency counter: 5
532 Unlearning counter: 43
533 Terminal_15_Kessy_specified_value: On
534 Terminal_15_Kessy_actual_value: On
535 Terminal_15_central_electric_actual_value: On
536 Terminal_15red_Kessy_specified_value: On
537 Terminal_15red_Kessy_actual_value: On
538 Terminal_S_Kessy_specified_value: On
539 Terminal_S_Kessy_actual_value: On
540 Terminal_S_central_electric_actual_value: On
541 Terminal_50_Kessy_specified_value: Off
542 Terminal_50_Kessy_actual_value: Off
543 ZAT_pressed: Off
544 Park selector lever position: Engaged and locked
545 Request active: Condition not met
546 Enabling steering column lock: Condition met
547 Enabling immobilizer: Condition met
548 No active error mode: Condition met
549 Key signature validity: Condition met
550 ---: 9.228 V
551 Driver information key position copy workshop: not active
552 Driver information, roll warning: not active
553 Driver information, emergency shutdown: not active
554 Internal_key_position: no_message
555 Driver information comfort switching: not active
556 Vehicle speed: 0.0 km/h
557 Engine speed: 136.0 1/min
558 ---: Vehicle unlocked
559 Approach to the inside: not active
560 Actuation to the inside: not active
561 Approach to the outside: not active
562 Actuation to the outside: not active
563 Pulling actuation, outside door handle: not active
564 Coding information: Not coded
565 Approach to the inside: not active
566 Actuation to the inside: not active
567 Approach to the outside: not active
568 Actuation to the outside: not active
569 Pulling actuation, outside door handle: not active
570 Coding information: Not coded
571 Approach to the inside: not active
572 Actuation to the inside: not active
573 Approach to the outside: not active
574 Actuation to the outside: not active
575 Pulling actuation, outside door handle: not active
576 Coding information: Not coded
577 Approach to the inside: not active
578 Actuation to the inside: not active
579 Approach to the outside: not active
580 Actuation to the outside: not active
581 Pulling actuation, outside door handle: not active

582 Coding information: Not coded
583 Driver door: Open
584 Front passenger door: Closed
585 Left rear door: Closed
586 Right rear door: Closed
587 Active_LF_scans: Init
588 ID sensor 1 authentication, status: No response
589 ID sensor 2 authentication, status: No response
590 ID sensor 3 authentication, status: No response
591 ID sensor 4 authentication, status: No response
592 SPN_Byte 0: 0
593 SPN_Byte 1: 0
594 SPN_Byte 2: 0
595
596

597 -----

598 BB Rear Left Door

599
600 System description: TSG HFS
601 Software number: 8W1959395D
602 Software version: 0187
603 Hardware number: 8W1959395D
604 Hardware version: 003
605 Serial number: YE007SAE0229D
606 ODX name: EV_DCU2RearDriveMAXHKLO
607 ODX version: 001010
608 Long coding: 000000200100020000001000
609
610 Trouble codes:
611 B122D29 - Lock unit for central locking Implausible signal
612 Intermittent
613 Date: 2024-07-09 15:15:01
614 Mileage: 171520 km
615 Priority: 5
616 Malfunction frequency counter: 5
617 Unlearning counter: 45
618
619

620 -----

621 BC Rear Right Door

622
623 System description: TSG HBFS
624 Software number: 8W1959395D
625 Software version: 0187
626 Hardware number: 8W1959395D
627 Hardware version: 003
628 Serial number: YE007SAE0022C
629 ODX name: EV_DCU2RearPasseMAXHKLO
630 ODX version: 001010
631 Long coding: 000000200100020000001000
632
633 Trouble codes:
634 B122D29 - Lock unit for central locking Implausible signal
635 Intermittent
636 Date: 2024-08-08 09:33:39
637 Mileage: 171521 km
638 Priority: 5
639 Malfunction frequency counter: 1
640 Unlearning counter: 45
641
642

643 -----

644 CF Lane Change Assistant Left

645
646 System description: MRR1Rear
647 Software number: 3Q0907590G
648 Software version: 0530
649 Hardware number: 3Q0907590
650 Hardware version: H23
651 ODX name: EV_RearRadarS2BoschVW48X
652 ODX version: 001007
653 Long coding: 14C002
654

```
655      Trouble codes:
656      No trouble codes found
657
658 -----
659 D6 LED Module Left
660
661      System description: LED1L
662      Software number: 7PP941572AB
663      Software version: 0003
664      Hardware number: 7PP941572A
665      Hardware version: H09
666      ODX name: EV_LEDModLeftMELCOAU736
667      ODX version: 001004
668
669      Trouble codes:
670      No trouble codes found
671
672 -----
673 D7 LED Module Right
674
675      System description: LED1R
676      Software number: 7PP941572AB
677      Software version: 0003
678      Hardware number: 7PP941572A
679      Hardware version: H09
680      ODX name: EV_LEDModRightMELCOAU736
681      ODX version: 001004
682
683      Trouble codes:
684      No trouble codes found
```