



## Vehicle data

Vehicle ID no.  
WVWZZZ3CZFE007756  
Delivery date:  
2014-06-30  
Next main inspection  
0000-00-00  
Next exhaust emissions test  
0000-00-00  
Type  
365C9R

## History

Explain  
Reception date:  
2019-10-23  
Mileage:  
127098  
Order no:  
210057208  
Invoice no.:  
408141143

---

### Repair operation

#	Number	Description	Maintenance	Paint	Cause code	Package
1	01500000	GFF/Guided functions .	-	0000		0

### Part item

#	Number	Description	Quantity	Factory code	TG	PG	Cause code	Package
1	3AF807421B GRU	Cover	1.00		OWN		0	0
2	3AF807441B GRU	Cover	1.00		OWN		0	0
3	3AF807521D MI1	Spoiler	1.00		OWN		0	0
4	3AF807568 U34	INSERT	1.00		OWN		0	0
5	3AF807819A 9B9	Trim	1.00		OWN		0	0
6	3AF919491A	Bracket	1.00		OWN		0	0
7	3AF919491B	Bracket	2.00		OWN		0	0
8	3AF919492A	Bracket	1.00		OWN		0	0
9	3AF853827 MI1	Cover	1.00		OWN		0	0
10	3AF853828 MI1	Cover	1.00		OWN		0	0

Explain  
Reception date:  
2017-07-21  
Mileage:  
59792  
Order no:  
207540268  
Invoice no.:  
405927307

---

Repair operation

#	Number	Description	Maintenance	Paint	Cause code	Package
1	99330000	MALER-ARBEITEN	-	0000		0

Explain  
Reception date:  
2017-07-03  
Mileage:  
59792  
Order no:  
207482007  
Invoice no.:  
405927307

---

Repair operation

#	Number	Description	Maintenance	Paint	Cause code	Package
1	99320000	SPENGLER-ARBEITEN	-	0000		0

Part item

#	Number	Description	Quantity	Factory code	TG	PG	Cause code	Package
1	3AF854940 U34	Cover	1.00		OWN		0	0
2	3AF854950 U34	Cover	1.00		OWN		0	0

Explain  
Reception date:  
2017-06-01  
Mileage:  
59792  
Order no:  
207395426  
Invoice no.:  
405824155

---

Repair operation

#	Number	Description	Maintenance	Paint	Cause code	Package
1	99330000	MALER-ARBEITEN	-	0000		0

Explain  
Reception date:  
2017-05-26  
Mileage:  
59792  
Order no:  
207376869  
Invoice no..  
405824155

---

Repair operation

#	Number	Description	Maintenance	Paint	Cause code	Package
1	99320000	SPENGLER-ARBEITEN	-	0000		0

Part item

#	Number	Description	Quantity	Factory code	TG	PG	Cause code	Package
1	3AF854940 U34	Cover	1.00		OWN		0	0
2	3AF854950 U34	Cover	1.00		OWN		0	0

Explain  
Reception date:  
2017-04-26  
Mileage:  
59792  
Order no:  
207281006  
Invoice no..  
405752528

---

Repair operation

#	Number	Description	Maintenance	Paint	Cause code	Package
1	99330000	MALER-ARBEITEN	-	0000		0

Explain  
Reception date:  
2017-04-25  
Mileage:  
59792  
Order no:  
207275664  
Invoice no.:  
405752528

---

Repair operation

#	Number	Description	Maintenance	Paint	Cause code	Package
1	99320000	SPENGLER-ARBEITEN	-	0000		0

Part item

#	Number	Description	Quantity	Factory code	TG	PG	Cause code	Package
1	3AF854940 U34	Cover	1.00		OWN		0	0
2	3AF854950 U34	Cover	1.00		OWN		0	0

Explain  
Reception date:  
2017-03-21  
Mileage:  
56656  
Order no:  
207153081  
Invoice no.:  
11228160  
Remark  
Warranty/goodwill

---

Repair operation

#	Number	Description	Maintenance	Paint	Cause code	Package
1	06890199	FAHRZEUG GEPRUEFT	-	0000		0
2	23602699	MOTORSTEUERGERÄT UMPROGRAMMIEREN	-	0000		0

Explain  
Reception date:  
2015-10-20  
Mileage:  
32564  
Order no:  
140275  
Invoice no...:  
231594  
Remark  
Maintenance

---

Repair operation

#	Number	Description	Maintenance	Paint	Cause code	Package
1	01090030	Insp.w.Oil change (felx.) .	X	0000		0
2	85181950	Dust and pollen filter removed+inst	-	0000		0
3	01500000	GFF/Guided functions .	-	0000		0
4	04010000	MOBILITAETSVERSICHERUNG BIS ZUM NAE	-	0000		0
5	99999911	W-RAD MONTIERT (BIS 18")	-	0000		0
6	99999301	WAGEN GEWASCHEN	-	0000		0
7	27068950	Battery loaded	-	0000		0

Part item

#	Number	Description	Quantity	Factory code	TG	PG	Cause code	Package
1	103	OEL LONGLIFE III 5W30	4.30		6			0
2	N 90813202	Bolt	1.00		OWN			0
3	03L115562	Filterelem	1.00		OWN			0
4	1K1819653B	Dust filt.	1.00		OWN			0
5	111	SOLVENT PLUS MIT FROSTSCHUTZ	2.00		6			0

Explain  
Reception date:  
2015-01-06  
Mileage:  
141111  
Order no:  
135914  
Invoice no.:  
228023

---

Repair operation

#	Number	Description	Maintenance	Paint	Cause code	Package
1	64101900	Windscreen removed+installed	-	0000		0
2	99994003	5% KLEIN- UND VERBRAUCHSMATERIAL	-	0000		0

Part item

#	Number	Description	Quantity	Factory code	TG	PG	Cause code	Package
1	DA 00400000	2KKLEBST/PRIMER/AKTIVATOR	1.00		6			0
2	FO	FOTO	3.00		6			0
3	3AA845011ADNVB	Windscreen	1.00		OWN			0
4	3C0854327B 5AP	Strip	1.00		OWN			0
5	3C0854328B 5AP	Strip	1.00		OWN			0
6	1K0998559	Repair kit	1.00		OWN			0
7	V15	VIGNETTE 2015	1.00		6			0

Explain  
Reception date:  
2014-06-26  
Mileage:  
25  
Order no:  
135186  
Invoice no.:  
502522

---

Repair operation

#	Number	Description	Maintenance	Paint	Cause code	Package
1	01010000	Delivery inspection .	-	0000		0
2	99999999	FAHRZEUG-REINIGUNG	-	0000		0

Part item

#	Number	Description	Quantity	Factory code	TG	PG	Cause code	Package
1	FT0000250	SOLVENT	1.00		OWN			0
2	BE	DIESEL	66.30		6			0
3	100	VIGNETTE	1.00		6			0

